

Technical Data Sheet

DESCRIPTION AND RECOMMENDED USES: 100% solids, **Dura-Coat Abrasion Fast 351** is a solvent free, **FAST CURING** ceramic filled coating designed particularly as a protective coating for metals in highly aggressive environments especially high wear abrasion. Excellent in a wide array of caustics and acids. **Dura-Coat Abrasion Fast 351** can be easily applied by plastic squeege or putty knife up to 500 mils without slump.

- It can be applied up to 500 mils without slump
- Suitable for any substrate, steel, bronze, aluminum, concrete
- Suitable for corrosion and abrasion protection
- Designed for rebuilding worn parts



Application Areas:

✓ Pipe el	bows	

- ✓ Screw conveyors
- ✓ Propelers
 ✓ Fans and ho
- Chutes and hoppers
- ✓ Fans and housings
 ✓ Wear plates

✓ Pump cases
✓ Bins
✓ Many others

✓ Impellers
✓ Coal crushers

TECHNICAL DATA

TECHNICAL DATA				
Maximum Temperature	Wet Service	70°C	158°F	
(Dependent on service)	Dry Service	93°C	200°F	
Chemical Resistance	Water	Excellent		
	Alkalis	Excellent		
	Inorganic Acids	Good		
	Organic Acids	Good		
	Organic Solvents	Good		
Flexural Strength	(ASTM D 790)	560 kg/cm2 (54.2 MPa)	8,000 psi	
Pull-Off Adhesion	(ASTM D 4541)	330 kg/cm2 (32.4 MPa)	4,700 psi	
Tensile Strength	(ASTM D 638)	240 kg/cm2 (23.4 MPa)	3,400 psi	
Shore D Durometer Hardness	(ASTM D 2240)	85		
Taber Abrasion CS-10, 1000g,	(ASTM D 4060)	35mg		
1000 Cycles				
Pot life		25 MIN / KG at 72ºF		
Vertical SAG Resistance at 21C		No sag		
(70F) and 12.7mm (500mils)				
Coverage for 10Kg kit	25sf @80mils	2.3m2 @2mm		
Mix Ratio	2:1 by Weight		Base: Activator	
Color	Grey as standard. Blue and Red optional. Other colors contact the manufacture			
Shelf life (unopened containers)	3 Years at 55-95ºF (13-35ºC)			





Application Sheet

Surface Preparation

Proper surface preparation is critical to the long-term performance of this product. The exact requirements for surface preparation vary with the severity of the application, expected service life, and the initial substrate conditions. All sharp edges and welds shall be ground smooth or to a 3 mm (120 mil) radius before abrasive blasting. Optimum preparation will provide a surface thoroughly cleaned of all contaminants and roughened to an angular profile between 75-125 μ m (3-5 mil). This is normally achieved by initial cleaning and degreasing and then abrasive blasting to a cleanliness of White Metal (SSPC-SP10) or Near White Metal, followed by removal of residual abrasive blast residues from the surface to be coated.

Mixing

Thoroughly mix Activator into Base with mixing stick or drill with low speed mixing blade scraping sides and bottom of container or mixing board. Mix by Weight 2-parts Base to 1-part Activator. Mix thoroughly to produce an even colored and streak-free material. **THINNING: Never thin**.

Application

Use heavy plastic squeegee or putty knife to apply a 1mm minimum thickness. Work material into profile of substrate to achieve maximum adhesive and to remove any entrapped air. Contour to correct form with putty knife or plastic applicator. If mold or form is used be sure to coat its surface with a release agent to prevent adhesion of the material.

Application Temperature: Keep between 55 to 95°F (17 to 35°C). Substrate: keep between 45 to 105°F (7 to 40°C). the difference in temperature of the substrate and the material should never exceed 10°F, 5°C. Substrate shall be a minimum of 5°F (3°C) above dew point. Do not apply if relative humidity exceeds 90%. If necessary, heat the metal prior to surface preparation using electric heater or heat lamp. Never use gas, oil, or kerosene heaters as they will leave a greasy residue on metal surface. For best results keep all material in warm area overnight (75°F+) for ease of mixing.

Curing Scheudle			
	16°C (60°F)	25°C (77°F)	32°C (90°F)
Tack Free	45min	30 min	20 min
Light Load	1 hrs.	45 min.	30 min
Overcoat End	1 hrs.	45 min	30 min
Full Load	1.5 hrs.	1 hrs.	45 min.
Full Chemical	4 hrs.	3 hrs.	2 hrs.

Curing Schedule

Clean Up

Use commercial solvents (Acetone, Xylene, Alcohol, Methyl Ethyl Ketone) to clean tools immediately after use. Once cured, the material would have to be abraded off.

Safety

Before using any products, review the appropriate Safety Data Sheet (SDS) or Safety Sheet for your area. Follow standard confined space entry and work procedures, if appropriate.

Manufacturer, Dura-Coat Industrial Inc., makes no warranty either expressed or implied including warranties of merchantability or fitness for a particular purpose for this product. Under no circumstances will the manufacturer be liable for incidental, consequential, or other damages, breach of warranty, strict liability, or any other theory arising out of use of this product. The information and or recommendations contained herein are based on standard Product and are proprietary and furnished solely for the use of our customers. This information is provided in good faith and believed to be true and accurate as of the date/version of this product, the manufacturer has no control over the use conditions or application process of the parties using this product, the manufacturer rannot accept responsibility for loss, injury or other damages resulting from the use of the Product or this or any other information provided by the manufacturer. Therefore, no guarantees of any kind, expressed or implied, are made by the manufacturer. DURA-COAT* epoxy products do not provide structural integrity or improvement. They are only used to provide protection from coss of use attects on a given substrate and only to the extent provided for in the Data Sheets, Technical Data Sheets, Stefty Data Sheets, and any other information and only to the extent provide for in the Data Sheets, Stefty Data Sheets, and any other information applied in writing directly from manufacturers.

